FEB 1952 31-488

no pot circulate

CENTRAL INTELLIGENCE AGENCY

UBJECT Ship Construction and Repair at Mathias NO. OF PAGES 2 NO. OF ENCLS. 50X1-HUM NECONITION OF THE CONTROL MATERIAL SERVICE TO A MATERIAL SERVICE TO		CLASSIFICATION SECRET/CONTROL - U.S. SECURITY INFO			50X1-HUM
OUNTRY East Germany UBJECT Ship Construction and Repair at Mathias NO. OF PAGES 2 MATE OF ROLE. ACC COURSED LACE COURSED LACE COURSED LACE COURSED THIS IS UNEVALUATED INFORMATION THE PROPERTY TO REPORT NO. THIS IS UNEVALUATED INFORMATION THIS IS UNEVALUATED INFORMATION THIS IS UNEVALUATED INFORMATION SOX1-HUM TElanned Actual Deckyard No. 10000 13.56 10.45 13.56 10.45 13.56 10.45 20. The Progress of Shipbuilding - Type I ships A. The state of completion achieved TElanned Deckyard No. 10000 13.56 10.45 13.56 10.45 20. The Progress of Shipbuilding - Type I ships A. The state of completion achieved TElanned Actual Deckyard No. 10000 13.56 10.45 13.56 20. The Progress of Shipbuilding - Type I ships A. The passons why the planned completion stage was not resched is explained mainly by a shortage of materials and a lack of specialists, particularly welders. 2. Refits of Russian ships A. The Progress of Shipbuilding Ships A. The Progress o		INFORMATION	REPORT	REPORT	
UBJECT Ship Construction and Repair at Mathias Thesen Werft, Wismar ATE OF NO. OF ENCLS. 50X1-HUM SUPPLEMENT TO REPORT NO. THE STATE AND THE ADMINISTRATE APPEARS IN THE ANTIQUE STATES. THE STATE AND THE ADMINISTRATE APPEARS APPEARS ARE THE ADMINISTRATE APPEARS APPEARS ARE THE ADMINISTRATE APPEARS APPEARS ARE THE ADMINISTRATE APPEARS APPEARS APPEARS ARE THE ADMINISTRATE APPEARS APP		1		CD NO.	
These Werft, Wismar NO. OF ENCLS. SUPPLEMENT TO REPORT NO. SUPPLEMENT TO REPORT NO. THIS IS UNEVALUATED INFORMATION ACCOUNTED TO A SECRET STATE. THE STATE OF THE ACCOUNTED TO A SECRET STATE. THE PROGRESS OF Shipbuilding - Type I ships A. The state of completion achieved Dockyard No. 10000 13.56 10.45 13.56 4.3 b. The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. 2. Refits of Russian ships a. The POREDA has left for Odessa. Before leaving the ship was provided with 200 tons of disselfuel whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft for a floating crane SOX1-HUM CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY	OUNTRY	East Germany		DATE DISTR. 10 Oct	ober 1952
SUPPLEMENT TO REPORT NO. SUPPLEMENT TO REPORT NO. THIS IS UNEVALUATED INFORMATION THIS IS UNEVAL	UBJECT	Ship Construction and Repair at Mathia: Thesen Werft, Wismar	3	NO. OF PAGES	2
THIS IS UNEVALUATED INFORMATION The Progress of Shipbuilding - Type I ships a. The state of completion achieved Dockyard No. 10000 13.56 13.56 Dockyard No. 10000 13.56 The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. Refits of Russian ships a. The Progress of Shipbuilding - Type I ships b. The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. Refits of Russian ships a. The Poesh has left for Odessa. Before leaving the ship was provided with 2200 tons of diesel fuel whereas only 1300 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the 500 and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Teipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY	ATE OF NFO.			NO. OF ENCLS. 5	0X1-HUM
THIS IS UNEVALUATED INFORMATION The Progress of Shipbuilding - Type I ships a. The state of completion achieved Dockyard No. 10000 13.56 10.45 1.156 The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. Refits of Russian ships a. The POBEDA has left for Odessa. Before leaving, the ship was provided with 3200 tons of dieselfuel whereas only 1800 tons had been authorized by the reparations office. Although 300 tons where returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA— This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in ita own vehicle from Teipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane SIATE X NAYY X NASE DISTRIBUTION	LACE CQUIRED		, 		
a. The state of completion achieved Actual	F THE UNITED S ND 794, OF THE ATION OF ITS (TATES, WITHIN THE MEANING OF TITLE 1B, SECTIONS 793 : U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVE- ONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS	THIS IS UNEVAL	UATED INFORMATION	50X1-HUM
a. The state of completion achieved RElamed Actual				• • •	200/(11101)
Dockyard No. 10000 13.56 10.45 4.3 b. The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. 2. Refits of Russian ships a. The POBEDA has left for Odessa. Before leaving, the ship was provided with 2200 tons of dieselfuell whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA—This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane SOX1-HUN CLASSIFICATION SECRET/CONTROL - U.S. OFFICIAIS ONLY	1.	The Progress of Shipbuilding - Type I s	hips		
Dockyard No. 10000 13.56 10.45 b. The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. Refits of Russian ships a. The POBEDA has left for Odessa. Before leaving the ship was provided with 2200 tons of dieselfuel whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane SOX1-HUN CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY		a. The state of completion achieved		was as follows:	50X1-HUM
b. The reasons why the planned completion stage was not reached is explained mainly by a shortage of materials and a lack of specialists, particularly welders. 2. Refits of Russian ships a. The POBEDA has left for Odessa. Before leaving the ship was provided with 3200 tons of dieselfuel whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA— This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane SOX1-HUN CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY		r.	anned	Actual	٠.
Refits of Russian ships a. The POBEDA has left for Odessa. Before leaving, the ship was provided with \$200 tons of dieselfuel whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane SCLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY		i. —		. 2	v -
a. The POBEDA has left for Odessa. Before leaving the ship was provided with 2200 tons of dieselfuel whereas only 1800 tons had been authorized by the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane SOX1-HUN CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY		b. The reasons why the planned complet mainly by a shortage of materials and a	ion stage was lack of speci	not reached is expl alists, particularl	ained y welders.
special consisting the second particles of the reparations office. Although 300 tons were returned, this event and the fact that extra work had been carried out on the vessel over and above the plan, have caused differences of opinion between the SCC and the Werft. b. KOOPERATSIA- This ship, back at the Mathias Thesen Werft, has not been completed in time. This is said to be a result of: (1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane SOX1-HUN CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY	2.	Refits of Russian ships			
(1.) the delayed docking of the vessel; (2.) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3.) the pressing need of Mathias Thesen Werft for a floating crane 50X1-HUN CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY	*	reparations office. Although 300 tons that extra work had been carried out on	300 tons had bo were returned, the vessel ove	en authorized by this event and the	he fact
(2) the nondelivery of the engines which Mathias Thesen Werft had to pick up in its own vehicle from Leipzig; (3) the pressing need of Mathias Thesen Werft for a floating crane 50X1-HUN CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY STATE X NAVY X NSRB DISTRIBUTION		completed in time. This is said to be a	a result of:	en Werft, has not b	een
(3) the pressing need of Mathias Thesen Werft for a floating crane 50X1-HUN CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY STATE X NAVY X NSRB DISTRIBUTION	*				
CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY STATE X NAVY X NSRB DISTRIBUTION	.00	(2.) the nondelivery of the engines wh in its own vehicle from Leipzig;	nich Mathias Th	nesen Werft had to p	ick up
CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY STATE X NAVY X NSRB DISTRIBUTION	*.	(3) the pressing need of Mathias Thes	sen Werft for a	floating crane	
STATE X NAVY X NSRB DISTRIBUTION		<i>*</i>		*	50X1-HUM
DIGINIBUTION DIGINIBUTION		CLASSIFICATION SECRET/CONTROL - U.S. C	FFICIALS ONLY		
, , , , , , , , , , , , , , , , , , ,	STATE	X NAVY X NSRB DISTRIBUTIO	ON N		

	SECRET/CONTF	OL - U.S. OFFICE	IALS ONLY		
		_ = 2 =			`
(4.) the	fact that work rowed from the	ers had had to u	use primitive	methods, i.e.	pontoons
possible on the another Object,	KOOPERATSIA. and the divisi m competitions,	teps are being this includes the on of the preser into three shift and supplies are	ne transfer o nt workers, w îts. In addi	f two welders ho are to be s tion, the issu	from purred ing
e. MOZHAISKI - has assured the	Minister Gerha SCC that the v	rd Ziller of the	livered this	year	
the delivery of proposed to bri in order to do	turbines by Be ng riveters em as much work as sen Werft is ag	hat he will make rgmann-Borsig ployed on bridg possible on her ain hampered in	e himself per ge building t during the	In addition of work on the long summer dang the vessel by the	sible for n, it is MOZHAISKI vs.
transfer of the	KALININGRAD (s	ork was carried ee below), all t to the MOZHAISKI	the resulting	r, in the even free manpower	would
	- The ship lef			e where the bo	50X1-HUM
were removed. the lack of a f	This work could loating crane.	not be done in Although the KAL the work will be	the Mathias ! ININGRAD is be	Thesen Werft b ckin Wismar. i	ecause of
the SCC an to which dock s	nounced that th he should enter ININGRAD, but o	ey were expectin . The SCC theref nly in such meas	ng advice from	m Moscow short d the Werft to	cease be ready
for immediate to	ransfer.				50X1-HUM
for immediate to f. ZESTRONEZK. If	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	the KCO PERATSI	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared t	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared tge this.	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared tge this.	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared tge this.	GDA and 50X1-HUM o take
f. f. ZESTRONEZK. If KALININGRAD is	ransfer. , as anticipated transferred, the	, the KOO PERATSI Mathias Thesen	irs are the 'A leaves show	rtly, and the be prepared tge this.	GDA and 50X1-HUM o take

Sanitized Copy Approved for Release 2011/05/09 : CIA-RDP82-00457R014100140001-3 50X1-HUM

Sanitized Copy Approved for Release 2011/05/09 : CIA-RDP82-00457R014100140001-3

SECRET/CONTROL - U.S. OFFICIALS ONLY